



▷ ENIG process: Electroless Nickel Immersion Gold → UBM




▷ Solder ball jetting




▷ Fully Qualified with SwitcherB18v2.0

- ↳ Test production
- ↳ X-sections, shear tests, test assemblies ... all ok!
- ↳ Assembly of EMCs, pilot modules, Desy test..





# SwitcherBv2.1 bumping

- ▷ Bumping (UBM process) causes problems with the new Switcher
- ▷ On one pad – the substrate pad – and only on this pad
  - ↳ Very little or no Nickel deposition
- ▷ Main difference to old Switcher
  - ↳ Different passivation (1µm Nitride/Oxide <-> PI)
  - ↳ Guard ring of the chip exposed, connected to bulk









- ▷ Different electrochemical potential causes reduced Ni growth on substrate
- ▷ **Trials** with isolated edge **failed** in batch process, workaround(s) **failed/not reliable**



# Bumping on "wafer level" at IZM

- ▷ Assemble a "wafer" by pick-and-place of Switchers to support with alignment marks
  - ↳ Accuracy good enough for 150 $\mu$ m pitch, subsequent wafer level lithography possible
  - ↳ Possibility to apply standard technology bumping by electro-plating



## Prozessschritte bei IZM:

- Design des Carrierwafers mit Alignmentmarken
- Design des Rekonfigurierten Wafers mit Bumpingmaske
- 2x 9" Lithographiemaske (external vendor)
  
- Strukturierung der Alignmentmarken auf dem Carrierwafer
- Assembly der Chips auf dem Carrierwafer
- Sputtern der Platingbase
- Resist-Lithographie
- Galvanische Abscheidung von UBM oder UBM+SnAg-Bumps (max. 20µm Gesamthöhe)
- Entfernen von Resist und Platingbase
- Reflow
- Ablösen der Chips vom Carrierwafer
- Reinigung und Sortieren in Gel Packs

## Task 1: Setupbatch mit ca. 30 Chips

Prozessierungsdauer: voraussichtlich 10 Wochen

Fixed Price: 15000, - €



## Task 2: Folgebatch nach erfolgreichem Abschluss von Task 1 (Design+Masken aus Task1):

Prozessierungsdauer: voraussichtlich 8 Wochen


Fixed Price (500 Chips): ca. 16000, - €

# SwitcherBv2.1 bumped at IZM

- ▷ Reconfigured Wafer and after seed layer deposition and lithography



- ▷ The bumped chip after reflow







## BELLE II- Switcher tests

Switcher Chips	Read JTAG ID	Bias Current	Boost Current	64 HV-channels
18	✓	✓	✓	✓
1	✓	✓	✓	✗
5	✗	✗	✗	✗

# Traces from probe card testing at KIT




# Cross section of IZM bumps







# Residues from electro-plating?





Not clear, under investigation





- ▷ Scratches from tweezers,  
most likely from our side
- ↳ Re-packing, probing...
- ▷ **Needs improvement, is probably the main yield killer**

## Next steps

- ▷ Flip chip trials at HLL with IZM bumped SWBs
  - ↳ Shear tests, cross sections ...
  
- ▷ New modules being prepared
  - ↳ DCDB4.2, DHPT1.1, SWB2.1 from the IZM pilot batch
  - ↳ W37-IB, W31-OB2
  - ↳ Expected back from flip chip in 2<sup>nd</sup> week of January
    - ↳ SMD and Kapton till end of January
  
- ▷ 439 unbumped chips now at IZM
  - ↳ For reassembly of 8 wafers, then bumping...
  - ↳ Handle wafer preps started
  - ↳ Aggressive time schedule: chips hopefully available till end of February
  
- ▷ Fall back
  - ↳ If flip chip trials or new modules show problems, stop processing → problem!
  - ↳ New wafers with SWB2.1 ordered (?)
  - ↳ Important: try to get them on wafers, **needs negotiations with broker/ams**
  
- ▷ If all goes well, start production mid/end March (time scale of DHPT1.2b)







# The recently assembled modules



## 4 modules assembled

- ▷ W31-IB, W31-OB, W31-OF
  - ↳ DCDB4.2 (final), SWB2.1 (final, repaired bump), DHPT1.1
  
- ▷ W31-IF
  - ↳ DCDB4.2 (final), SWB2.0 (last samples of the old version), DHPT1.1



- ▷ Flip Chip without any anomalies
  - ↳ Switcher generally not prime grade due to problems with bumping (see next slide)
  
- ▷ SMD, Kapton attachment as usual



# Status of the modules as of today




- ▷ **... n.b.: this is work in progress**
- ▷ W31-IB and W31-OB:
  - ↳ JTAG configuration fails as soon as the Switchers are in the chain
- ▷ W31-IF:
  - ↳ JTAG configuration okay,
  - ↳ functional so far, see effect of bad substrate bump on the Switchers (3/6 SWBs)
- ▷ W31-OF (with SWB2.0):
  - ↳ JTAG okay
  - ↳ Functional so far, under test and optimization
- ▷ There is no completely clear picture what went wrong with these modules
  - ↳ Many new components on the modules
    - ↳ SWBs, DCDB4.2, new kapton, new patch panel and cables, new firmware
    - ↳ Many suspects ...
- ▷ **Tests and debugging is ongoing!!**


# "fishy" Switchers, though tested okay

Modul W31-IB

Switcher 1



Folie 3



Belle Pixeldetektor




Ausrichtung des Moduls

X-Rayanalyse, 02.07.2013, Berlin

Modul W31-IF


Switcher 5




Leiterbahn beschädigt

Belle Pixeldetektor

Modul W31-OB1



Switcher 2



Switcher 3

Switcher 3

Switcher 3

- SWBs show imperfections, scratches
- flip chip was done, since the tests on chip level were positive





- detailed xray inspection after FC showed no anomalies (apart from the Au stud bump)

Folie 7



# Test Assembly of SWBs to bond adapter

- ▷ Adapters assembled for SWB testing on hybrid level
  - ↳ Three adapters assembled
  - ↳ One assembly done with bad chip (bumping problems)
- ▷ Cross-section



- ▷ Delamination between SWB Alu and Ni?
  - ↳ Not certain that is this real
  - ↳ Could be due to contamination before UBM....

# Test Assembly of SWBs to bond adapter

