



Hybrids: Status report

07. Feb. 2011

6th International Workshop on DEPFET Detectors
and Applications

Christian Koffmane^{1,2}

¹Max-Planck-Institut für Physik, München

²TU Berlin, Faculty IV of Electrical Engineering & Computer Science, Chair of Sensor and Actuator Systems

● Overview



Hybrid 4.1.x


- Functionality of the Hybrid 4.1.x
- Bring-up of the Hybrid 4.1.x Boards
- Hybrids 4.1.x Overview
- Preparations for the assembly of PXD6

Mini Matrices

- Preparations for the assembly of PXD6


PXD6/PXD5 Hybrid Board H4.1

- 2 x **SwitcherB** to address
 - either a full PXD6 matrix (small matrix 128 x 16)
 - or a part of a PXD5 matrix (128 x 128)
- DCD-B/DCDRO read out
- DEPFET Matrix directly bonded to ASICs/wire bond adapters




PXD6/PXD5 Hybrid Board H4.1

- 2 x **SwitcherB** to address
 - either a full PXD6 matrix (small matrix 128 x 16)
 - or a part of a PXD5 matrix (128 x 128)
- DCD-B/DCDRO read out
- DEPFET Matrix directly bonded to ASICs/wire bond adapters




● PXD6/PXD5 Hybrid Board H4.1

- 2 x **SwitcherB** to address
 - either a full PXD6 matrix (small matrix 128 x 16)
 - or a part of a PXD5 matrix (128 x 128)
- DCD-B/DCDRO read out
- DEPFET Matrix directly bonded to ASICs/wire bond adapters



● PXD6/PXD5 Hybrid Board H4.1

- 2 x **SwitcherB** to address
 - either a full PXD6 matrix (small matrix 128 x 16)
 - or a part of a PXD5 matrix (128 x 128)
- DCD-B/DCDRO read out
- DEPFET Matrix directly bonded to ASICs/wire bond adapters



● PXD6/PXD5 Hybrid Board H4.1



Issues during the bring-up:


- PCB had to be re-work
 - One via wrongly connects power planes and GND
 - Repair was done at HLL and the PCB manufacture

- Clear Switcher
 - On three hybrid boards the clear switcher is not functional
 - JTAG programming not working
 - Further analysis needed (as mentioned by Ivan)

● PXD6/PXD5 Hybrid Board H4.1

Issues during the bring-up:


- DCD-B
 - ADCs characteristic distorted
 - Link between FPGA and DCDRO broken



● Hybrid Board H4.1.01


Issues during the bring-up Hybrid 4.1.01:

- Bond-wire Connection between Gate and Matrix




- Hybrid Board H4.1.01

Clear Switcher




Gate Switcher



● Hybrid4.1.01: Read/Clear Sequence


Step	Sequence
0	switch on Switcher Channel gate 0 -> read signals from Matrix double row 1 switch on Switcher Channel clear 0 -> clear Matrix double row 0
1	switch on Switcher Channel gate 1 -> read signals from Matrix double row 0 switch on Switcher Channel clear 1 -> clear Matrix double row 1

- No matrix channel was operated in its normal mode of operation during the TB2010!
- Explains effects we see in the TB data:
 - Clear inefficiency
 - Gain difference between odd and even rows




- Re-bonding of Hybrid 4.1.01

Gate Switcher re-bonded in CW4:




● First results after re-bonding Gate Switcher

- Noise and Common Mode are smaller as in the beam test
- A very preliminary number for $gq = 280 \text{ pA/e-}$
→ some very new results will be shown by Benjamin tomorrow!




Further source measurements
will be done!

● PXD5/PXD6 Drain Current



PXD5 - characteristic



Simplified Input of the DCD-B

- PXD5 and PXD6 drain current are expected to be around $100\mu\text{A}$ (same W/L) without irradiation
- DCD-B internal current source is designed for $70\mu\text{A}$ and thus limits the DEPFET drain current – TC1 is designed for $140\mu\text{A}$
- g_q is proportional to Drain current


● Hybrid 4.1.x




Hybrid Number	Components Mounted	Status	Location
H4.1.00	DCDB/DCDRO, SWB x 2	DCDB not working	Mannheim
H4.1.01	DCDB/DCDRO, SWB x 2, PXD5 Matrix COCG LB	DUT Beam Test 2010	HLL
H4.1.02	DCDB/DCDRO, SWB x 2, PXD5 Matrix COCG LB	Clear Switcher did not work right after assembly	Mannheim
H4.1.03	DCDB/DCDRO, SWB x 2, assembled in Bonn	DCDB & SWB, no PXD yet	Bonn
H4.1.04	DCDB/DCDRO, SWB x 2	DCDB & SWB, no PXD yet	HLL
H4.1.05	DCDB/DCDRO, SWB x 2	DCDB & SWB, no PXD yet	HLL
H4.1.06	DCDB/DCDRO, SWB x 2	DCDB/DCRO: Digital Injection Test failed - communication problem between FPAG and DCDB	HLL

● Preparations for PXD6

- Mechanical dummies are ready since CW5
- Assembly tests have been started:
 - set parameters for bonding



● Mini Matrix Preparations for PXD6



- PCBs for PXD6 Mini-Matrices are available
- Dummy Matrices are also available
- Assembly tests will be started soon

● Summary




- Hybrid 4.1.x
 - Lot's of things learned
 - First read-out of PXD5 Matrix with DCDB and SwitcherB as steering chips
 - Assembly and test of further hybrid boards is ongoing (in Bonn, Mannheim and Munich)

- Preparation for PXD6 is started using dummy matrices



Hybrid 4.2.x



SwitcherB
Wirebond
Adapter for
Clear

SwitcherB
Wirebond
Adapter
for Gate