



# FW/BW Subassembly Report

(an update since June B2GM)



S. Bettarini on behalf of the Pisa SVD Group



VXD Workshop, SVD session - Trieste, Sept. 10, 2015

# Introduction

- Class A Subassembly production started in mid-July at the foreseen rate
- Standard production conditions such to verify rate at "regime" not yet reached:
  - Interleaved some class B+ subassemblies
  - Need to build one more class C SFW+SBW for TIFR
  - Summer holidays
- So far, parts in Pisa are such to arrive well beyond Christmas. To reach the completion of the SA production:
  - Already agreed on the 3<sup>rd</sup> small hybrid production (32 hybrids 8 of each type for the end 2015)
  - 3<sup>rd</sup> PA-Flex production to be received

# Recent shipments

- Before the summer holidays:
  - 2 class B+ SFWs (001,002) + 2 SBWs (003, 005) all built with parts under IPR sent to KEK using the final custom "procedures"




- Cost optimization mandatory: in future, shipments will be optimized, by sending 9 SA at the same time (using new bigger boxes).

# Iterated Request to the ladder sites

- Each subassembly leaving Pisa has stored (DB):
  - the mechanical measurements by the survey after the gluing
  - the results of the el. characterization, laser scan and the output of the automatic defect finder
- It's important to perform asap at destination:
  - Quick optical survey on the MPC (z-side up)
  - I-V curve (assessing no severe damage due to shipping)
  - El. Characterization (no bonding pulled off due to vibration/mechanical stress during the shipping): please upload the calibration data into the DB
  - The SA check-list has been extended to host these tests at the sites
  - Spotting new opens should be straightforward also in case of different noise levels due to the different set-up @ the sites.
- We need to monitor continuously any (un-expected!) failure caused by an abnormal handling during the shipping.

# Mechanical measurements

## Sub-assembly - Reference systems




All reference systems were changed, using as new origin one of the F-marks of the sensors. They are marked with "(0,0)" in the pictures above. Also the new nomenclature of reference points was set. A file which contains all the gluing coordinates of every sub-assembly is always used.

So far, all the subassembly we produced matched the mech. tolerances!

# The latest and upcoming shipments

- Shipped (31<sup>st</sup> Aug) the class C for L5:
  - SBW to Vienna
  - SFW(closing IPR) to CERN
- Shipment planned (14<sup>th</sup> Sept.) the class C for L4:
  - SBW to IPMU
  - SFW(closing IPR) to KEK
- In mid-August Received the 2<sup>nd</sup> prod. batch of Flex-PA from KEK (IPR):
  - The cover-layer/glue survey is in progress this week (so far all the 36 PB1 and 39 PF1 are ok, continuing this week)
- The whole picture of the site schedule is needed to optimize the future shipment.



# SFW production status

(updated on Tue. 8<sup>th</sup> Sept.)

Code	Tags	State	Item Quality	
<input type="checkbox"/>	<u>SFW009</u>	<u>N-side glued</u>	<u>Class A</u>	FAILURE
<input type="checkbox"/>	<u>SFW984</u>	<u>N-side measured</u>	<u>Class C</u>	Under bonding; to be shipped to KEK (closing IPR) for L4 on Sept. 14 <sup>th</sup>
<input type="checkbox"/>	<u>SFW008</u>	<u>N-side measured</u>	<u>Class A</u>	To be bonded
<input type="checkbox"/>	<u>SFW007</u>	<u>N-side measured</u>	<u>Class A</u>	To be bonded
<input type="checkbox"/>	<u>SFW006</u>	<u>P-side bonded</u>	<u>Class A</u>	Under el. test (*)
<input type="checkbox"/>	<u>SFW005</u>	<u>P-side bonded</u>	<u>Class A</u>	Under el. test (*)
<input type="checkbox"/>	<u>SFW004</u>	<u>ready for shipment</u>	<u>Class A</u>	El. Characterized
<input type="checkbox"/>	<u>SFW986</u>	<u>fully tested</u>	<u>Class C</u>	To be used for mech. tests in Pisa (not IPR)

(\*) delay due to teststand problems

# SBW production status

(updated on Mon. 8<sup>th</sup> Sept.)

	Code	Tags	State	Item Quality	
<input type="checkbox"/>	<u>SBW009</u>		<u>N-side measured</u>	<u>Class A</u>	To be bonded
<input type="checkbox"/>	<u>SBW983</u>		<u>P-side bonded</u>	<u>Class C</u>	Bonded; to be shipped directly to IPMU (no IPR) for L4 on Sept. 14 <sup>th</sup>
<input type="checkbox"/>	<u>SBW008</u>		<u>N-side measured</u>	<u>Class A</u>	To be bonded
<input type="checkbox"/>	<u>SBW007</u>		<u>P-side bonded</u>	<u>Class A</u>	Under el. test (*)
<input type="checkbox"/>	<u>SBW006</u>		<u>laser scanned</u>	<u>Class A</u>	El. Characterized
<input type="checkbox"/>	<u>SBW004</u>		<u>laser scanned</u>	<u>Class A</u>	El. Characterized
<input type="checkbox"/>	<u>SBW001</u>		<u>P-side bonded</u>	<u>Class B</u>	El. Characterized; many noisy channels. To be further studied
<input type="checkbox"/>	<u>SBW988</u>		<u>unset</u>	<u>Class C</u>	To be used for mech. tests in Pisa



# Results

## SFW004 SUMMARY SBW004 SUMMARY SBW006 SUMMARY

### P-Side

number of defects = 4 / 768 (0.52%)  
# pinholes = 1 / 768 (0.13%)  
# opens = 0 / 768 (0.00%)  
# shorts = 0 / 768 (0.00%)  
# noisy strips = 2 / 768 (0.26%)

### P-Side

number of defects = 9 / 768 (1.17%)  
# pinholes = 1 / 768 (0.13%)  
# opens = 1 / 768 (0.13%)  
# shorts = 0 / 768 (0.00%)  
# noisy strips = 7 / 768 (0.91%)  
# bad laser strips = 0 / 768 (0.00%)

### P-Side

number of defects = 9 / 768 (1.17%)  
# pinholes = 0 / 768 (0.00%)  
# opens = 0 / 768 (0.00%)  
# shorts = 2 / 768 (0.26%)  
# noisy strips = 7 / 768 (0.91%)  
# bad laser strips = 0 / 768 (0.00%)

### N-Side

number of defects = 10 / 512 (1.95%)  
# pinholes = 3 / 512 (0.59%)  
# opens = 0 / 512 (0.00%)  
# shorts = 0 / 512 (0.00%)  
# noisy strips = 3 / 512 (0.59%)

### N-Side

number of defects = 8 / 512 (1.56%)  
# pinholes = 0 / 512 (0.00%)  
# opens = 0 / 512 (0.00%)  
# shorts = 0 / 512 (0.00%)  
# noisy strips = 7 / 512 (1.37%)  
# bad laser strips = 1 / 768 (0.13%)


### N-Side

number of defects = 5 / 512 (0.98%)  
# pinholes = 0 / 512 (0.00%)  
# opens = 0 / 512 (0.00%)  
# shorts = 0 / 512 (0.00%)  
# noisy strips = 5 / 512 (0.98%)  
# bad laser strips = 0 / 768 (0.00%)

# Preliminary Report on the failure of SFW009


- In the survey performed on Tues. 8<sup>th</sup> Sept. we discover that half the subassembly is un-bondable because glue spread on almost half the bonding pads on the z side.
- We are investigating:
  - The Z gluing was performed on Mon. 7<sup>th</sup> afternoon by the “best team” (on SB’s opinion).
    - The mechanical alignment of PA-Det-Hybrid was correctly done (see survey before gluing);
    - the glue deposition didn’t show any problems.
    - The Z gluing operations finished with the team apparently “happy” of the result.
    - The glued was seen to spread uniformly and it reach the 1st pad’s row in the few most critical regions (as usual).
  - The day after we found that the vacuum (on the det’s chuck) was wrongly switched off. Clearly the detector raised when the glue was still liquid (i.e. not cured) and it caused the abnormal squeezing of the glue.
  - Some-ONE inadvertently switched OFF the vacuum after the final positioning of the jigs was reached
  - From the survey after the gluing the final relative position AP-Det-Hybrid didn’t change wrt what recorder before the gluing
- We have still to understand more to take the right action to prevent that such a thing might happen again.
- Somehow we have to re-think and modify our procedures to make them more robust against (this kind of) accidents.

# Some snapshots of the accident on SFW009



# Future plots monitoring production

When a greater statistics is available (i.e. for the next B2GM) I will preparing integrated "luminosity" plots, i.e.:



Also useful a similar plot for needed parts:

- Hybrids/sandwiches (tested)
- Flex-PA (surveyed)

## Subassembly Gluing: Rate = 2 SBWs + 2 SFWs / week

h	Monday	Tuesday	Wednesday	Thursday	Friday
9	Gluing SBW1-P	CMM survey+photo SBW1-P	CMM survey+photo SBW1-N	CMM survey+photo SBW2-P	CMM survey+photo SBW2-N
		Transfer to Z jig SBW1-P	Transfer to MPC SBW1-N	Transfer to Z jig SBW2-P	Transfer to MPC SBW2-N
10		Gluing SBW1-N	Gluing SBW2-P	Gluing SBW2-N	
	P-Glue dispensing				
11					
		N-Glue dispensing	P-Glue dispensing	N-Glue dispensing	
12					
13					
14	Gluing SFW1-P	CMM survey+photo SFW1-P	CMM survey+photo SFW1-N	CMM survey+photo SFW2-P	CMM survey+photo SFW2-N
		Transfer to Z jig SFW1-P	Transfer to MPC SFW1-N	Transfer to Z jig SFW2-P	Transfer to MPC SFW2-N
15		Gluing SFW1-N	Gluing SFW2-P	Gluing SFW2-N	
	P-Glue dispensing				
16					
		N-Glue dispensing	P-Glue dispensing	N-Glue dispensing	
17					

Spare Time (prepare shipments)				
Glue curing time:	22.5h	21.5h	22.5h	21.5h
Glue curing time:	22.5h	21.5h	22.5h	21.5h
P-side gluing: 2.5h				
N-side gluing: 3h				

Needed: 8 x (4h)-shifts + 2 x (1h)-shifts  
 Shift Crew: 1 Physicist+1 technician OR 2 Physicists

Microbonding					
h	Monday	Tuesday	Wednesday	Thursday	Friday
9	SBW0-Z bonding	SFW0-Z bonding	Hybrid sandwich assembly(3HSB+3HSF)	SBW1-P bonding	SFW1-P bonding
10					
11					
12					
13					
14	SBW0-P bonding	SFW0-P bonding	SBW1-Z bonding	SFW1-Z bonding	Hybrid sandwich assembly(3HSB+3HSF)
15					
16					

Legenda:

SBW0            the 2nd SBW glued the previous week  
 SFW0            the 2nd SFW glued the previous week  
 SBW1            the 1st SBW glued the current week  
 SFW1            the 1st SFW glued the current week

Spare Time

ManPower:        0.9 AProf  
 (technicians)    0.2 PMam

In the first period of production we are experiencing a low bonding speed ...

Not easy to match the technician holidays with production, especially during the summer.

Electrical Test and Laser Scan					
h	Monday	Tuesday	Wednesday	Thursday	Friday
9	SFW-1		SBW0	SFW0	SBW1
10					
11					
12					
13					
14		Hybrid			
		Sandwiches			
15		Test			
		6HSB+6HSF			
16					
17					

Legenda:

- SFW-1      the 1st SFW glued the previous week
- SFW-0      the 2nd SFW "
- SBW-0      the 2nd SBW "
- SBW1      the 1st SBW glued the current week






Spare Time

- Needed:      8 x (3.5h)-shifts    w/o automatic    procedure
- 4 x (3.5h) shifts    w "                    "
- 1 x (3.5h) shift    for HS test
- Shift Crew:    2 Physicists

With the introduction of the automatic procedure in the SA el. tests, 1! Shift is needed to characterize a subassembly and resources can migrate to gluing.

# BW/FW sub-assembly developed tools

- **Hybrid gluing jigs:** sandwich single side hybrids
- **Gluing jigs:** det $\leftrightarrow$ PA $\leftrightarrow$ hybrid  
Required high planarity for the chucks  
Two (detector and hybrid) towers raising to squeeze the glue on the PA
- **Multi Purpose Chuck:** designed for bonding/testing sub-assemblies in Pisa and their safe shipment (Z-side up). P-side up MPC are used to perform upside-down operation.
- **Transfer jigs:** to safely transfer the subassembly
  - after the the P-side gluing to the MPC, perform the upside-down operation and take that on the Z gluing jig
  - after the Z-side gluing to the MPC






# FW/BW sub-assembly production status (8 Sept.)

So far, not considering the class “D” subassemblies, Pisa produced (with final procedure and jigs):

- Backward
  - 3 class C SBW (before Pisa review in Oct. 2014)
  - 6 class C SBW (5 for the Ladder Sites + 1 for Pisa mech. Test, 1 under bonding)
  - 3 class B SBW
  - 4 class B+ SBW (1 to be further studied)
  - 5 class A SBW (2 el. characterized, 1 under el. test, 2 to be bonded)
- Forward
  - 3 class C SFW (temporary jigs used)
  - 1 class B SFW (the test-beam one, temporary jigs used)
  - 6 class C SFW (5 for the Ladder Sites + 1 for Pisa mech. Test, 1 under bonding)
  - 2 class B SFW
  - 3 class B+ SFW
  - 6 class A SBW (1 ready, 2 under el. test, 2 to be bonded, 1 failure)

# Sub-assembly electrical characterization and laser-scan

- After the unique bonding phase (N&P side w/o any intermediate test) a complete electrical test is foreseen with the sub-assembly Z-up on the MP chuck, to eventually spot new defects (and verify the known ones!).
- The final qualification of the sub-assembly is the functional characterization by a laser scan.



- Giulia reported that on Sept. 3<sup>rd</sup> between the calibration tests and the laser scan the test-stand experienced a "failure":
  - ADC Delay Scan returns delays with differs up to 4 ns;
  - with Internal Calibration Run on the reference hybrids, several warnings (one each event) arose.
- Standard working condition found on Sept. 8<sup>th</sup> by Eugenio without any modification/actions!

# Micron det's ESD packaging (left Pisa on June 24)





+ HPK # 83 to be tested  
(after wrongly  
using that to tune chucks)

These detector will be returned to Pisa (not shipped but safely carried by hand) on Fri. 11st September, with some mechanical piece (cooling pipe, MPCs) received from Vienna.

# PA chuck under the gluing robot

The positioning of the PA chuck(s) under the gluing robot can be precisely moved, by installing the x-y/theta stages:




Now small variations of the position of the PAs on their chucks can be easily accommodated (the 2 holes on the PA are precise at 50  $\mu\text{m}$  level) w/o touching the tip of the syringe. Test program have also been improved.

# Measurement of trigger and clock resistors on hybrids

For L5.001 class B ladder in the SVD meeting Sept 1st has been announced:

- Defect resistor on SFW003
  - Defect appeared during electrical test after it was glued onto ribs.
  - Worked fine during incoming inspection.
  - Extra samples in row data of p-side APV25 chips.
  - Calibration run was no more possible.
  - Caused by reflections due to broken 100 Ohm resistor (terminator) between trigger lines.
  - Resistor could be replaced.
  - Now the module works fine again.


The defect has been found on  
HSF005 hybrid sandwich (p-side)  
= H6+P067 single hybrid




After that warrisome failure, we started a campaingn of measurements of the resistors between **trigger** lines (5-6) and **clock** lines (9-10)

# Measurement of trigger and clock resistors of FW+BW hybrid sandwiches

All available hybrid sandwiches (class A, not yet used for subassemblies)  
have been tested: 20 forward + 20 backward = 80 resistors



The resistors that have been measured  
(100  $\Omega$ , with 1% of nominal tolerance)




The setup used to perform the  
measurement

**No broken resistors have been found (so far...)**

# Measurement of trigger and clock resistors of FW+BW hybrid sandwiches

Distribution of all measured resistors




From this sample:

average =  $\mu = 101.3 \Omega$   
st. deviation =  $\sigma = 0.5 \Omega$

The single distributions (e.g.  
forward p-side trigger, etc.) have  
a similar trend

The lead resistance (cables, connectors, etc.) has  
been evaluated with the  
4-wires probes method (by Keithley 2001)  $1.2 \Omega$




$$R = 100.1 \pm 0.5 \Omega$$

Only one measured resistor (not shown in the plot above!) is  
far more  $3\sigma$  from the average value (see next slide)

# Measurement of trigger and clock resistors of FW+BW hybrids

The clock resistor of HSF010 p-side (= H6+P065) is  $104.1 \Omega$  ( $5.4\sigma$  from the average value!)


An **optical inspection** has been made under the microscope




The resistor seems  
"sane"

HSF010 has passed  
the electrical test

All other resistors as  
well observed are OK  
under optical inspection  
(there aren't visible  
defects)



Finger-print of the  
sandwich mask (with white  
paint)



Still to do the measurements on:

1. the 2nd batch hybrid boards (before the el. test and sandwich gluing)
2. the class A SFW and SBW already produced (please do the same @IPMU on the new 4 class B+ subassemblies)

A "mechanical" damage by the sandwich mask can be excluded