

# L6 Status Report

Takeo Higuchi, Kavli IPMU (WPI)

*A few update since Onuki-san's report  
in the last SVD meeting, on Sep. 1<sup>st</sup>.*

# L6 Ladders

- **After the 7<sup>th</sup> VXDWS up to the L6 QCG review**
    - **Class-C ladder**
      - L6.903 ... called “class-C++” in the L6
    - **Class-B<sup>-</sup> ladder**
      - L6.901 ... called “class-B<sup>-</sup>” in the L6
- Reviewed by the QCG on Jul.27<sup>th</sup>, 2015
- **After the L6 QCG review**
    - **Class-C ladder (ongoing)**
      - L6.905 ... started from Sep.4<sup>th</sup> with the SVD group approval.



# L6 QCG Review Report

- **Summary of the review report summary**
  - The procedures should be adjusted and finalized.
    - In particular, the issue related to the large shift in the SFW.
  - The procedure changes should be reflected in the document.
  - Produce one class-C.
    - The mechanical results should be reported to the QCG.
  - Produce one class-B using the final procedures.
  - The final review should be held right before the class-A start.

# Actions for the Recommendations

- **FW sensor shift**


- Reason: the FW sensor was dragged forward (even the vacuum chuck) if the HB was moved beyond the critical region in the HB position adjustment.
- Solution: limit the HB positioning within the allowed region.
- Verification: the sensor movement has become much smaller than that was observed in the B<sup>-</sup>.



See Onuki-san's slides in the SVD meetings on Aug.25<sup>th</sup> and Sep.1<sup>st</sup> for more detail.

# FW Sensor Shift

- So far, we got aware of the following sources
  - The hybrid dragging presented in the previous page.
  - Fixing pin precision:



Loose pin precision can introduce the  $\sim 100\mu\text{m}$  shift. We ruled it out from reasons of our particular issue; however, we will replace the pins with tighter ones.


Y. Onuki (Aug.18<sup>th</sup>)

- *If you have aware of the other points to be cared, please let us share them.*


# Actions for the Recommendations

- **Wrapping procedure finalization**

– Original




Lower the FlexPA  
downward



Record the FlexPA  
height touching  
the PA0



Preset the target height  
= recorded height +  
glue thickness (50µm)



Lower the glued  
FlexPA downward  
**to the target height**

- Issue: glue spread was not reproducible.
- Solution: take the preset value just as a hint; the stop position is determined by watching the actual glue spread.
- Verification: the wrapping becomes stably reproducible with giving the  $\varepsilon_{WB} = 100\%$ .

# Actions for the Recommendations

- **Documentation**

- All of the final procedures have been reflected in the flowchart and working manuals.

1.	Flowchart
2.	Housekeeping
3.	Parts preparation
4.	incoming item check
5.	SPA production
6.	RSA production

7.	Sensor alignment
8.	FW/BW gluing to the RSA
9.	AIREX/Origami gluing
10.	Wrapping
11.	Ground wire soldering



**The final  
procedures have  
been reflected.**



# Actions for the Recommendations

- **Documentation**


- The visual check points are discussed and implemented in the working manuals.
- The photographing points are as well.
- Printed working manuals are ready in the clean room.
  - They are being referred to in the ongoing class-C assembly.




# Additional Study – Origami Bending

- **Origami\_+Z bending**
  - The bending procedure must be justified before the class-B, because the class-B is our first/last R&D ladder with the Origami\_+Z bent by the latest procedure.
    - The class-C will employ the crack-PA0 Origami.
  - The last mockup Origami\_+Z was bent by the latest procedure; it was glued to the “partial” ladder assembled for the FW sensor shift study.


# Additional Study – Origami Bending




The “partial” assembled used for the FW sensor shift study.




Right after placing the O+Z on the ladder.




Placing a CO<sub>2</sub> clip on the SFW with an AIREX piece glued.



The finished “partial” ladder.




The Origami\_+Z is properly sitting on the DSSD+AIREX.




The DSSD F-mark is visible from the F-mark hole.

# EQA – Incoming Item Test

- **Origami** (O+Z003, OCE008, O-Z001 of the class-C)
  - “Smooth” curves of the cal. scan and ped. noise  $\leq 2$ .



Cal. curves of the O+Z003



Ped. noise of the O+Z003



- **SFW/SBW** (SFW991, SBW985 of the class-C)
  - *I*-*V* curve measurement in addition to the APVDAQ check.

# EQA – Radioactive Source Test

- **Radioactive ( $^{90}\text{Sr}$ ) source test**
  - New software to get the strip-by-strip sensor hit map is available ... to be used to debug the system.
  - The “aDefectFinder” was tried; the manual is prepared.
  - The 1MBq  $^{90}\text{Sr}$  (x100 than now) will be available on Oct.9<sup>th</sup>.
    - The paper work has been finally finished.
    - Expected source test speed from a 20-hour run using the 10kBq source → 2 hours / sensor for >1k hits / strip.

# EQA – Radioactive Source Test

- **Radioactive ( $^{90}\text{Sr}$ ) source test**
  - The diagonal scintillator-arm motion has been implemented.
    - 200 secs per round trip.
    - Origin of the stage controller has been adjusted to the +Z DSSD corner.
  - A 2cm-thick acrylic spacer will be attached to the container bottom to move the ladder upward.
    - The ladder interferes with the scintillator-arms now.



**More elaborated spacer is preferred.**

# EQA

- **Issues**

- Procedures are being finalized, while we need more experience of countermeasures.
  - Some channels show much smaller heights in the calibration curve of the class-B<sup>-</sup> SFW989.
    - The SFW passed the incoming parts check properly.
    - The low pulse height suggests short circuits, but we do not see damaged WB in the SFW.
  - Half of a certain APV25 in the class-B<sup>-</sup> became silent.
  - There is a single isolated strip that has low noise.
    - Cannot be a short circuit.

# Class-C Production

- **The class-C has been started from Sep. 4<sup>th</sup>.**
  - The L6 class-C production was approved in the SVD meeting on Sep. 1<sup>st</sup>.
  - Progress so far:

Date	
Sep. 4 <sup>th</sup> (Fri)	<ul style="list-style-type: none"><li>• Briefing, inventory check, clean room tidying up</li><li>• DSSD planarity check</li></ul>
Sep. 5 <sup>th</sup> (Sat)	<ul style="list-style-type: none"><li>• Origami incoming check (EQA/visual) ... O+Z003, OCE008, O-Z001</li><li>• RSA production ... RS6.903</li><li>• SPA production (gluing) ... SPA6.910, SPA6.911, SPA6.912</li></ul>
Sep. 6 <sup>th</sup> (Sun)	<ul style="list-style-type: none"><li>• <i>Break</i></li></ul>
Sep. 7 <sup>th</sup> (Mon)	<ul style="list-style-type: none"><li>• SPA production (WB)</li></ul>
Sep. 8 <sup>th</sup> (Tue)	<ul style="list-style-type: none"><li>• SFW/SBW incoming check (EQA/visual) ... SFW991, SBW985</li></ul>


# Schedule

- **The ongoing class-C (L6.905)**
  - We plan to finalize the L6.905 assembly and mechanical survey in the week of Sep.14<sup>th</sup>.
  - We would report the L6.905 results in the SVD meeting on Sep.22<sup>nd</sup> if the production will have been completed along the schedule.



# Ladder Subgroup Issues (1)

- Clarify exactly what redundant wire bonds should be done.
  - [TH] According to the discussion in the L3 site review on Aug.21<sup>st</sup>, I remember more than 4 bonds in total for the bias line. *Is my understanding correct?*



# Ladder Subgroup Issues (2)

- **Incoming Origami test**
  - Visual inspection of the bonds
  - APVDAQ test
  - Bias and clock line connectivity ... use the dedicated card
- **Should define a procedure to verify the proper adjustment of the slider stiffness ... L5 report**
- **Should define a procedure to discuss the sensor shift in case the sensor F-marks are covered by something and cannot be viewed by the CMM.**

**Thank You**