





IB/OB JTAG Puzzle

- ▷ After checking all first order suspects (r/o system, PS, grounding, re-test of SWBs ...)
- ▷ Detailed x-ray inspection, cross sections ...
- ▷ No anomalies, no "smoking gun"



- ▷ All SWBs from W31-OB2 have been removed today (manual de-soldering)




Pads on Module after removal


Switcher 1-6 →




SWB1



SWB2



SWB3






Pads on Module after removal


Switcher 1-6 →




SWB4



SWB5



SWB6



Hi-Res pictures at <http://hll.mpg.de/~lca/temp/W31-OB2-after-SWB-removal/>



Conclusion, possible reasons, mitigation

- ▷ Going from SWB1 → SWB6 wetting gets worse towards SWB3 and 4, then better towards SWB5 and 6
- ▷ Possible reasons
 - ↳ Reflow temperature not reached in the middle of the module due bad contact to the heat plate
 - ↳ talk to IZM....
 - ↳ In this case a second (local) reflow with HCOOH or flux might help
 - ↳ BCB (final passivation, solder stop) residues on the pads
 - ↳ Inhomogeneous „descum“ (plasma process is worse at bottom and at the edge of the wafer..)
 - ↳ Needs cross check,
 - ↳ possibly more descum, currently we remove 300-400 nm of BCB after final passivation