



SC Status



Michael Ritzert


michael.ritzert@ziti.uni-heidelberg.de

22nd International Workshop
on DEPFET Detectors and Applications

Ringberg

09.04.2018

- Alarms
- GUI
- PS Firmware
- PSC




Some clarifications:

- Sole addressee of alarms is the shifter.
 - ⇒ Only objective: Keep the system producing good data.
 - It's not a reminder tool for experts.
 - Two well-defined alarm levels:
 - **MAJOR**: System is broken.
 - **MINOR**: Do something *now* to prevent MAJOR.
- ⇒ no MINOR without MAJOR possible.
We might not have many MINOR alarms.
- DQM will provide valuable inputs:
 - PXD operation is judged by the data that come out.
 - If in doubt: If data are fine, all is well.
 - Unfortunately, this means there's a delay between failure and alarm.
 - ⇒ get from BonnDAQ what's also available there?

What Happens When an Alarm Fires?

- Sound Notification in the Control Room.
 - Obviously requires speakers.
- Alarm visible in the respective views.
- Action guidelines for the shifter available in the context menu.
 - List of things to try. Last item usually „Call ... expert.“
- Only one possible action: Let the IOC do it automatically.
 - Unless the state of the system should not be changed for inspection by the experts. Use sparingly.
 - Log entry as „FYI“ to the shifter. Shown on PXD top panel.
- Probably no upstream integration (to Belle 2):
No compatible system used.



First Alarms Are Active

Alarm Tree

phase2

- Area: ONSEN
 - System: 001
 - System: 001M1
 - PV: PXD:001M1:IN-DC-NPIr-HeaderErr
 - PV: PXD:001M1:OUT-ROI-NPIr-Heade
 - PV: PXD:001M1:IN-DC-NPIw-Framingl
 - PV: PXD:001M1:OUT-ROI-NPIw-Framir
 - System: 003

manual action 1
manual action 2
Copy to clip-board

Could add actual instructions directly here.
But long instructions could be misinterpreted.

- First draft of shifer-overview panel and a few levels of hierarchy in PSC.
 - Inspired by outcome of discussion with Botho.
 - Next level: (Half-)expert panels for more detailed overview and task-oriented view, i.e. all information/buttons required to perform a task.
- Widely accessible, no expert-only information.
- It's not possible to run 40 units manually.
No provisions for that are foreseen.

- To be hosted on pxdgw1.
 - Check into one repository, get precompiled output in another repository.
 - git ⇒ mirroring to outside of KEK possible.
Read-only copy in stash @ DESY if required.

PXD Top GUI


The screenshot displays the 'PXD Overview' interface with several control panels:

- Cooling:** Includes 'on' (green indicator), 'set point -20.0 C', and 'stable' (green indicator). An 'OPI...' button is present.
- Power Supply Control:** Shows 'Belle II' (Disconnected) and 'PXD' (OFF) status. It includes a 'global run' checkbox, an 'Interlock' (green indicator), and an 'OPI...' button.
- Run Control:** Shows 'Belle II' (READY) and 'PXD' (NOTREADY) status. It includes a 'global run' checkbox and an 'OPI...' button.
- Environment:** Shows 'Dew Point Margin' and an 'OPI...' button.
- Event Size Trigger Rate:** A large blue rectangular area labeled 'DQM'.
- ConfigDB:** A large blue rectangular area labeled 'DQM'.
- PXD Alarm:** A pink box labeled 'Disconnected'.
- PXD Message Log:** A table with the following entries:

Timestamp	Severity	Message
2018-04-06 22:12:42.701	WARNING	chip 0 does not support IDCODE.
2018-04-06 22:12:42.701	WARNING	chip 1 does not support IDCODE.
2018-04-06 22:12:42.701	WARNING	chip 2 does not support IDCODE.
2018-04-06 22:12:42.701	WARNING	chip 3 does not support IDCODE.
2018-04-06 22:12:42.292	SEVERE	No chain with this name in driver

Log entries \geq warning level \Rightarrow awareness of what's happening when things fail.
E.g. automated action by the alarm system triggered an error state.

PXD PSC GUI



left-click: descend.
right-click: go local, emergency shutdown.


Single Module GUI

PXD Module 1131

\$(title2)

Local Powersupply Control


Global Run Unit is disabled.



Power Chain

- module powered
 - PS interlock
 - PS OVP
 - PS connected
 - PS powered 0.85 A
 - power
 - primary power
-
-
-

Data Path



Temperatures

PS Unit	Disconn
DHH	38 C
DHP1	7.8 C
DHP2	-6.1 C
DHP3	1.3 C
DHP4	-4.2 C

remove


?

DQM?
BonnDAQ data?

to GUIs for DHH, PS, special tasks

- PS connected
- PS powered 0.85 A
- power
- primary power

PS current consumption (from Crate Controller).
VDouble[0.8502538800239563, 2018/04/06 23:53:3



At first: Everything according to plan with first real tests:


- Firmware successfully tested with two units (no modules) at KEK.
 - Parallel ramp-up/-down without problems.
- Several units flashed at DESY.
 - Flashing now really easy.
 - Routine power on/off cycles without problems.

BUT

- Frequent disconnections between firmware and IOC at KEK.
- Immediately visible symptoms:
 - Some ‰ of monitoring packets are not received by the IOC.
- Happens many times a day at KEK, not a single time in weeks in Heidelberg.
- At DESY, I do see „something“ once every couple of *days*.
 - Events involving both units within a few seconds, longer that at KEK.


Implications

- TCP connection for commands IOC \Rightarrow PS.
 - Effectively unidirectional communication.
 - ACK gets lost
 - \Rightarrow IOC retransmits the frame.
 - PS ignores the duplicate frame \Rightarrow no problem?
(Commands carry a sequence number, no discontinuity is detected.)
- UDP „connection“ PS \Rightarrow IOC.
 - Monitoring packets (voltage/current data).
 - No retransmission of lost packets
 - \Rightarrow IOC **drops the connection** on timeout.




Is It Very Bad?

- In principle: No.
- A patched IOC accepts three or four lost packets in a row.
 - ~800 ms monitoring period, timeout increased to 4 s.
 - Two lost packets in a row are a frequent event, more is very rare (at KEK).
 - The old firmware/PS has a 5 s timeout.
 - **RISK:** At DESY, events are much less frequent, but more destructive.
- Are there more implication I don't see, yet?




Debugging (Fixing?)

- Narrowed down to: An Ethernet frame is handed to the DMA engine for transfer to the MAC. It never shows up on the Ethernet.
- On the switch side, I see „FCS errors“ (Frame check sequence).
 - ⇒ the problem is between PS unit and switch!
 - Rate of occurrences depends strongly on switch type used.
 - Wrong checksum, etc. can be ruled out: Any receiver would reject that.
 - ⇒ the problem must be more „analog“.
- The old units do not show this behavior
 - ⇒ Now I know where to look for differences in the code.
 - But reading the old code is a nightmare.
 - And interpreting it then is yet another one.
- My personal favourite right now: Different configuration of the μ C-internal clock tree yields a slightly better PHY frequency output.
 - There a hardly any other settings that are not black/white good/bad.



How to continue?

- Option a) Ignore for now, use the patched IOC.
 - Accept the risk of occasional errors.
 - A fix can be developed without time pressure.
- Option b) Do not continue like this.
 - Safest way.
 - Totally unpredictable delay: Zero to „forever“. A fix might be one line of code found tomorrow or require fixes in the PS hardware.
- If the situation at DESY **with the new switch** is as at KEK, I'd probably go for a).
 - These are the units we will use in phase 3.
 - The entire rack will travel to KEK, including the switch.
 - ⇒ We know beforehand, what we'll get.
- Hardware for flashing is available at KEK.
 - Needs access to top of belle for ~2 minutes per unit.



- PXD is not yet connected to PSC. Waiting for
 - New PS firmware.
 - Full PSC interface spec from Belle 2 SC team.
- It has been proposed to participate at first by only reporting the state of PXD.
- The mapping from state to allowed type of injection is as below.
- We designed our PSC (i.e. power-up sequence) this way, so this could be a way forward.
- But merging the states from several PS needs some thought.

HV state mapping

(from Konno-san)

HV state	HV master	Continuous injection	Normal Injection
OFF	OFF	Allowed	Allowed
STANDBY	STANDBY	Allowed	Allowed
PEAK	PEAK	Allowed	Inhibited

Thank you!

- Quite unlike the events at KEK:
 - much less frequent than at KEK. Once every two days vs. once every hour.
 - two units almost(!) simultaneously
 - lasts for more than 4 seconds

```
2018-04-06 21:06:31.389 [warning] [active_u] Unit 53: monitoring delta 2612ms.
2018-04-06 21:06:32.389 [warning] [active_u] Unit 53: monitoring delta 3612ms.
2018-04-06 21:06:33.390 [warning] [active_u] Unit 53: Marked as dead.
2018-04-06 21:06:33.390 [warning] [communic] Unit 53: Dropping TCP connection
2018-04-06 21:06:33.390 [severe ] [LogRecei] Unit 53: Error in recv() : 0, 107
2018-04-06 21:06:33.391 [warning] [LogRecei] Unit 53: emergency_shutdown
2018-04-06 21:06:33.391 [warning] [LogRecei] Unit 53: SC connection lost.
2018-04-06 21:06:37.390 [warning] [active_u] Unit 60: monitoring delta 2493ms.
2018-04-06 21:06:38.390 [warning] [active_u] Unit 60: monitoring delta 3493ms.
2018-04-06 21:06:38.390 [info   ] [communic] Unit 53: TCP connected.
2018-04-06 21:06:38.391 [info   ] [LogRecei] Unit 53: TCP connection accepted.
2018-04-06 21:06:38.391 [config ] [communic] Unit 53: firmware version 'afe2128-dirty @ 2018-04-05T13:05'.
2018-04-06 21:06:39.390 [warning] [active_u] Unit 60: Marked as dead.
2018-04-06 21:06:39.390 [warning] [communic] Unit 60: Dropping TCP connection
2018-04-06 21:06:39.391 [severe ] [LogRecei] Unit 60: Error in recv() : 0, 107
2018-04-06 21:06:39.391 [warning] [LogRecei] Unit 60: emergency_shutdown
2018-04-06 21:06:39.392 [warning] [LogRecei] Unit 60: SC connection lost.
2018-04-06 21:06:44.391 [info   ] [communic] Unit 60: TCP connected.
2018-04-06 21:06:44.392 [info   ] [LogRecei] Unit 60: TCP connection accepted.
2018-04-06 21:06:44.392 [config ] [communic] Unit 60: firmware version 'afe2128-dirty @ 2018-04-05T13:04'.
```