

DHH and DHE Status

Igor Konorov

Institute for Hadronic Structure and Fundamental Symmetries (E18)

TUM Department of Physics

Technical University of Munich

PXD Workshop and 23rd International Workshop on DEPFET Detectors and Applications
May 28-th, 2019





DHE Firmware

DHE_20190314_1521 deployed on March 14-th

- Problem with first and last read out rows
- Problem with data throttling
- Limited diagnostics

DHE_20190511_1446 deployed on May 13

- Bug free so far
- Extended diagnostics
- DHP frame size limit is 2000 words
- Short reset during operation to recover DHP links
- Synchronization with DHP => frame and gate numbers reset at start of run otherwise free running

DHE_20190512_1110


- The same as 20190511_1446 but with different DHPT synchronization logic
- Synchronization with DHP => frame and gate numbers are taken from first active DHP when no triggers otherwise
 free running
- During first test one DHE was not working reliably for unknown reason, repeated test on May 27-th was successful
 Possible cause: UCF interface or programming sequence



Frame size limit

Maximum DHP frame size is limited to 2000 words

> 1616 pixels/DHP frame => not less than 3.3% occupancy





DHE Error Word

Error register divided to 4 fields:

DHP3(31-24), DHP2(23-16), DHP1(15-8), DHP0(7-0)

8 bits divided to 2 fields: 3-0 – Start of event, 7-0 – End of Event

Error codes:

x"0" - no errors

x"1" - missing frame

x"2" - timeout => GHOST frame


x"3" – dhp link down

x"4" – dhp masked

x"5" – trigger number mismatch

x"6" – data block too big







Stopped runs by PXD for last 5 days

Runs 1020-1335, 21.05-27.05 PXD Run Summary Elog

Error Type	# of stopped runs	# Phy. runs	Comment
H1051 data drop	19		2 times/shift
Other modules data drop	8		
Others DHH errors	1		UCF link
DHP link(s) drop	3		No stop of run
Other errors	7		
Total	35	174	

H1051 data drop error synchronous with CLOCK SYNC ERROR in DHI50



DHH To Do List

Minor changes in DHE firmware

Improve DHP synchronization information

Test of GATED Mode

Improving UCF link stability

Investigation of DHI 58 CLOCK Sync problem causes H1051 data drop

Activities during shutdown, July 7-23

- Test of Load balancing DHC firmware
- Installation of IPMC in all DHH carrier cards => remote power cycle of DHH modules
- Installation of new PC instead of SHROUD



THANK YOU



DHPT Problems

1. Case 1

- N consecutive high occupancy events take M frames to transmit data (M > N)
- After completion of data transmission DHP sends M-N empty frames with the same frame number => if trigger would arrive during this time the event will be empty

2. Case 2

- N consecutive high occupancy events may cause stop of DHPT, observed at TUM and DESY
- Recovery only by LONG RESET