

ONSEN Status in Phase 3

Simon Reiter

II. Physics Institute
Justus Liebig University, Giessen

PXD Workshop and 23rd International Workshop
on DEPFET Detectors and Applications,
May 2019



1 ONSEN status / features

2 ONSEN related issues

- ONSEN RC errors
- Missing HLT events at run start
- HLT processing time
- Incompatible module cabling
- Disabled DHH data checks

ONSEN status / features

- Currently only 1/8 of the full system in use
- Load Balancing tested with event builder
 - ▶ Activation of 1/2 system via slow control (IPMI) required
- ONSen firmware is running without problems!
- ONSen provides pixel count separated for each module
 - ▶ reveals spikes in occupancy at 2 Hz resolution (10 Hz possible)
 - ▶ But: does not allow masking of modules on the fly
- No tests with DATCON so far.

ONSEN related issues

ONSEN RC errors

"HLT ahead of DHH"

- Trigger number difference between incoming data of DHH and HLT is negative \Rightarrow HLT faster than DHH ?!
- Appears sometime simultaneously with other errors (see JIRA BIIPXDH-269)
 - ▶ reveals missing triggers from DHH (data flow stopped)
 - ▶ origin still unclear, situation improved with current firmware


"EB2 link loss"

- Event Builder 2 drops link to ONSEN
- Further investigation by Yamagata-san ongoing, but still unclear
 - EB2TX did receive nearly no update since phase 2, when it was never observed
- Might be chain reaction:
 - ▶ $\text{HLT} \rightarrow \text{EB2RX} \rightarrow \text{EB2TX} \rightarrow \text{ONSEN}$

ONSEN related issues

Missing HLT events at run start


- Missing events from HLT
 - ▶ some processes on worked nodes die
 - ▶ PXD data lost in ONSSEN memory
- Mainly happens at run start
 - ▶ 1000 events
- Check in ONSSEN is currently disabled, to prevent run stop after 4.2 M events
- Not problematic at current occupancy of 0.05%



ONSEN related issues

HLT processing time

- ONSEN memory designed for $< 5s$ processing time
- Not problematic at current occupancy at $\sim 0.05\%$ and trigger rate at $< 5\text{ kHz}$
- Situation will improve with load balancing
- Partly due to the initialization of basf2 ($\sim 30s$)
 - ▶ might improve in future by moving initialization to LOADING stage



ONSEN related issues

Incompatible module cabling

- No proper ROI selection possible
- Firmware design requires increasing DHE ID per DHC
 - ▶ required for matching IDs between data and ROIs
- Possible solutions:
 - 1 ~~Insert patch panel on top of Belle to disentangle combined fibers before reaching DHE~~
 - 2 Change order in DHC firmware

ONSEN related issues

Disabled DHH data checks

- Check of increasing DHE ID
- Check of correct Start of Row word in ZS frame
 - ▶ Showed connection to occupancy drops
- Check of DHP Frame ID
 - ▶ Frame ID to be in sync with Frame Number in DHE header (6 bits)

Activated since May 24th

- Check of trigger shift to previous event
 - ▶ will help to check if events have been skipped
 - ▶ will verify load balancing from DHH

Activated since May 24th

- Overall ONSEN runs very stable, no down times
- Only a few not urgent related issues

Thanks for your attention!

DHE ID of ROIs and DHH data have to be in ascending order.

Procedure in firmware:

- Extract DHE ID from DHH data stream
- Skip ROIs with lower DHE ID
- Gather all ROIs with same DHE ID and do selection