



PXD2 Module Assembly/Repair HLL

- status May 2022-



Code	state	remark
L1_61 - 55_IB & 52_IF	Kapton displaced at BWD	Kapton replaced on ladder ...
W59_OB2	Tested analogue	Had severe problems, used as guinea pig for Cu dip, Later resolved: was issue with probecard → class A module
W53_OB2	Tested analogue	got SWB2.1, broken SW1 repl. with SWB2.2, then changed back to new SWB2.1 passed all tests with 2 nd probe card → class A module
W44_OB2	w/o kapton	Seg. fault → kapton removal&reflow w/flux at DHPs, Kapton removed at MPP, reflow at DHPs done, seg. Fault gone but still JTAG config issues → set aside
W68_IF	Fully assembled → Bonn??	JTAG issue seen at DESY, verified at HLL - JTAG unstable, best option: → kapton removal&reflow w/flux at balcony, Kapton removed at MPP, reflow done, JTAG now stable → got kapton → ??
W60_IB (PXD9-20)	Fully assembled, kapton removed at MPP	tested with probe card after water damage → SWB Problem → needs replacement of all SWBs
W70_IF	Probe card tested → functional but "C grade"	got SWB2.1, many missing gate lines, probably sensor issue, only for backup/lab tests
W55_OB2	Probe card tested, failed, module lost	Module got SWB2.2, damaged at rework/excessive testing → module lost

▷ For today

↳ Few pictures from kapton replacement on ladder level




L1_61 history challenge



- ▷ Ladder assembled and passed all tests Nov. 2020
- ▷ Mounted on first PXD2 HS July 2021
 - ↳ **14 July 2021:** Tests on HS showed JTAG problem on BWD side (W55_IB),
 - ↳ Dismounted from HS
- ▷ Optical and x-ray inspection revealed displacement of kapton → wire bonds broken
 - ↳ Root cause unknown, possibly overheated during tests, not clear when this happened
 - ↳ On FWD side (W52_IF) no visible damage .. I guess ..
 - ↳ **12 July 2021: last test of FWD side before HS mounting, test after mounting??**

- ▷ Challenge
 - ↳ Replace kapton after ladder assembly → requires new procedure/tooling




- ▷ Procedure
 - ↳ Modify ladder jig to allow alignment of kapton to ladder
 - ↳ Mount ladder on modified jig (tooling available)
 - ↳ Remove old kapton on heat plate/hot air soldering
 - ↳ Modify tooling for kapton fixture to ladder during soldering
 - ↳ Design and produce new tool for rework station
 - ↳ Test and practice with dummy ladder





Kapton removal






- ▷ Modified ladder jig designed by David and manufactured at MPP
- ▷ Ladder removed from original jig and placed on new jig → remove old kapton
- ▷ 70 °C from below, further heat by hot air soldering from above
- ▷ Print solder pattern on new kapton






● kapton alignment and soldering

- ▷ Position kapton and fix kapton jig to ladder jig
- ▷ Place assembly in rework station using dedicated tool for heating
- ▷ Optimize temperature profile with dummy ladder





The result - Excellent cooperation between Carina (MPP) and Silvia (HLL)!!

- ▷ Temperature profile was set to have enough heat at one end ($\sim 170^{\circ}\text{C}$), keeping the other as cold as possible ($\sim 70^{\circ}\text{C}$)
- ▷ Three profiles necessary, with intermediate x-ray, to get best result



From 1st to 3rd trial



- ▷ Wire bonding without problems at MPP
- ▷ **BWD side fully functional again, but FWD side has now JTAG problems**
- ▷ **Needs follow up ... did not give up yet**
- ▷ **We can also exchange the FWD side if needed ... News from MPP??**

