


PXD Commissioning at DESY Experience P1

Transport MPP to HH


- A-team by car, kangoo, very slowly
- no (obvious mechanical) damages for dummy HS2
- still uncomfortable road conditions
→ use better rental next round




Mounting HS on dummy BP at DESY

- exercised by Reimer, Carsten, A-team following [checklist](#) → [pictures](#)
- procedure went smooth w/ issues
 - good to do w/ 4 people → might want to train additional expert

inspection
(incl ladder screw tests)



mount to BP



install to setup and
connect: CO2, N2, PPs







HS Mechanics: Issues (noticed) During Mounting

HS mechanics overall:

- HS looks very good: no brass vs SCBs angle, flat modules, so far no issue w/ opposite brass pieces, ...
- mounting procedure went rather smooth
- some (0(2)) ladder screws loose

Issues:

- scratches on L1 Kaptons
 - origin not known, so far no visible impact on module performance
- pipe bending still not perfectly along BP and dents in pipes (interference w/ heavy metal? flow?)
 - to be re-check for second HS
 - re-bending difficult (preserve cross section, ensure no cracks)
- metal specs on matrices
 - could remove some at DESY, though not all
- PP connection damage
 - bent pins during plugging, luckily on female side
 - luckily unproblematic channel, still need to be even more careful



PXD Services

PCs:

- HW quite old (still using temporary testbeam setup from 2016?!)
- some limitations, pray “good enough” and survives till October
 - eg network hiccups, slow pedestal upload, cant run optical switch ioc, ...
 - took some time to get archiver running stably

DHHs commissioning experience:

- configured / maintained with Stefans help (at DESY and remotely)
- some cards needed to be exchanged already (Stefan brought DHC30 replacement, used DHH20)
- needed (too) much time to get all stable links:
 - RTM issues, optical switch config, dirty fibers, poorly plugged fibers, unknown, ...
 - need to streamline procedure for KEK (prepare configs, define debugging procedures in advance)



PSU commissioning experience

- have 11 PSUs at the moment: 10 for HS, 1 for testsetup
- unfortunately had one PSU break while connected on HS module
 - 67 had issues in past, seemed to work ok at DESY, now at LMU for debugging
- repaired unit 51 by DESY workshop (exchanged IC and NMOS on DCDC board)
- many HS_2p4 modules run in dcd-avdd current limit
 - implications on performance unknown, have to decide how best move forward w/ proposed fix

MARCO C02 cooling experience

- ran smoothly until beginning of last weeks → then observed critical C02 pump error
- setup down since, waiting for experts (holidays, sick) to investigate issue

PXD Commissioning

Config DB:

- manually adjusted from DHE → DHC setup by hand (including some “homogeneization”)
- some errors (multiple source entries per module)


Hot DHP test:

- first powered all modules 1-by-1 w/ cooling
→ caught broken PP


Initial commit comparison to MPP:

- cold DHP→STANDBY→PEAK power up 1-by-1
- comparison to MPP measurements [cf](#)
- some understood differences in pedestals and power consumption
 - different op temperature
 - different power supplies used
 - purposely different config (gain setting → will do differently for 2nd HS)
 - wrong config entry used at DESY
- one not understood difference
 - probably bad offsets in DESY config db?
 - fixed by offset calibration


H1011: W54_IF



H2042: W46_OB1 (MPP used En60 branch, DESY En90)



H2052: W42_OB1 (difference not understood, consistent configs! Probably offsets issue?)




Calibration Scans

Goal (ideally):

- get high quality reference scans (incl temp dep and cross-talk)
- possibly recalibrate (eg offsets)
 - raw pedestals
 - offset calibration
 - hv-iv currents
 - depfet-iv currents
 - adc-curves(recalibration necessary for some HS_1p4 modules characterized at DESY)

Not yet reached at DESY



- lack in person power/time and module/scan knowledge
 - many modules need special treatment
- lack in luck / measurement script robustness
 - many modules \Rightarrow higher chance of error (OVP, corrupt data)
 - complicated cooling & interlock \Rightarrow higher chance of errors
- may have impact on commissioning at KEK
 - less time but still may want reference measurements at final operation conditions
- IMO worth spending time also to gain/retain recalibration flexibility for irradiated modules (ADC scan, offsets, ...)





Offset (Re-)calibration




- aim to get good offsets (in particular for “old” modules)
- results mostly **good** but some **bad**
 - algorithm still not handling dead drainlines & problematic offset lines well
 - something strange w/ disconnected drainlines




weird constant ADC values




Pedestal Maps







Pedestals Distributions HSa



Pedestal Distributions Hsb




Pedestal Noise




Special Needs Module H2011 / W45_OF1


- Shows weird “glitchy” behaviour were pedestals of ASIC-pair 2 shift in some regions for individual gate
- issue not understood, dcd-avdd was particularly low for this module
- issue significantly mitigated by exchange of **DHE/DHI & PSU**
 - module mostly operational, further investigations pending



noise behaviour:
pixel wise and
correlated pedestal
jumps in both dirs



multiple glitch patterns?




Advanced Calibrations

adc calibration


- might want to repeat as some DESY modules were not correctly characterized!
- possibly also study cross-talk or temperature dependence
- test scripts for KEK to study ageing behaviour
- despite further improvements to code, remains challenging:
 - module preconfiguration, good scan range for all modules
 - data issues (!) and OVPs!
- so far: only working point measurement for [HsA successful](#) :(
 - in principle scripts work for multiple DHCs!

gradeA: 7231 / 10000
gradeB: 2740 / 10000
dead: 29 / 10000



further calibrations

- depfet iv → not yet attempted
- source calibration → Anselm's talk



*sorry, Munira, but I gotta prove a point here

Summary

We're muddling through...

HS Mechanics:

- transport and mounting rather smooth w/ some headroom for 2nd HS

Commissioning:

- Would've wished for fewer problems and a bit more systematic approach
 - hopefully have learned for 2. HS and commissioning at KEK
 - will continue w/ hopefully more person power
 - could hide a bit behind delayed schedule
- Overall HS_2p4 modules seem as healthy as during characterization
 - sole exception H2011 / W45_OF1 which remains a mystery
(still, as long as 2nd HS not ready, contemplating exchange futile)
- Will continue w/ some basic calibration scans and mostly source measurements
 - hope best starting state of HS and good knowledge of it will pay out in the long run

Source Setup Operation:

- mostly smooth from PXD and cooling perspective
- unfortunately still some misoperations that should be avoided
(eg power on w/ light in setup → source current limit)
- unfortunately: recent MARCO issue remains to be investigated and fixed
 - issue could not be reproduced w/ engineers today
 - will try continue testing asap

