ONSEN SC, RC, IPMI – Status and Issues

Björn Spruck, Uni Mainz

Ringberg 9.4.2018

No Issues.

- No problems with RC (also noted in report on 5.2.18 by Yamada-san)
- ONSEN monitoring o.k.
 - Ready for Phase 2, input/ouput monitoring as needed
- Using "precompiled" OPI for ONSEN, IPMI, PXDRC. No problems detected.

- Some cosmetic suggestions (colors, logos, ...)
- Remark: Same GUI is used in Giessen for "full setup" tests
- Cosmetics; new features added if needed
- Display glitch on NSM side; NSM bridge does not handle/detect disconnects
 - Fixed in NSM bridge code, but not used
- Some annoying delay until PV gets valid (heartbeat) after FPGA reprogram
- IPMI IOCs need to be restarted if hardware changes

Summary

PXD RC, ONSEN RC, ONSEN SC, ONSEN IPMI already designed for full PXD operation

IOHANNES GUTENBERG

- Scalability proven in lab setup
- \rightarrow No modification needed for Phase 3
- TODO: EPICS upgrade
- Remark: EPICS 7 is part of basf2 externals since v01-06-01
 - Needed for DQM \rightarrow SC \rightarrow Alarmsystem
- Ongoing work:
 - Implement new (hardware) features
 - Non expert GUI
 - Alarms



 All ONSEN/DATCON IPMI hardware (MMC and IPMC) production was finished before TB 2016

JOHANNES GUTENBERG

- EPICS / Slow control / CSS was used for IPMI monitoring (boards and shelf) since then
 - Sensor reading by IOC based on ipmitool
 - IOC to send commands to boards (e.g. reprogram FPGA)
- Different shelves are in use, each with different sensors:
 - DHH ATCA Shelf (2 slot) with Kontron Shm700
 - DHH ATCA Shelf (6 slot) with Kontron Shm700
 - ONSEN ATCA Shelf (2 slot) with Kontron Shm500 (lab)
 - ONSEN ATCA Shelf (14 slot) with Kontron Shm500 (lab)
 - ONSEN ATCA Shelf (14 slot) with Kontron Shm500 (final one)
 - ONSEN ATCA Shelf (14 slot) with Kontron Shm500 (borrowed for Phase 2)
 - DATCON MicroTCA Shelf with NAT MCH-Base12-GbE
- For each of these, EPICS database files and OPI have been created
- Reworked db structure for maximum synergy

- Updates on IOC: prevent timeouts and performance bottlenecks
- Parallelize IOCs: one IOC per carrier + one for shelf, (limited by maximum connections to Shelf Manager)


- Concerns: IPMB bus collisions and recovery
 - Collisions normal for 2-wire bus with >10 masters, should be recovered automatically (in silicon!), but its not always working
- Test full shelf over several weeks → no IPMI related problem found

JOHANNES GUTENBERG UNIVERSITÄT MAINZ JG U

• ONSEN Upgrade

- IPMC for new Belle2 ONSEN Carrier Board designed.
 - Carrier follow PICMG rules more strictly
 - Solves some workarounds needed in current firmware
 - No problems expected
- MMC controller for new RTM
 - Same hardware, only minor software changes
- Some strange behaviour on DHH Shelves found
 - Remote Shutdown **dangerous** to boards without IPMC
 - Fans turn off but power keeps on.
 - Some quirks in FRU sensor (would raise a false alarm in monitoring).
- IPMI for DHH Carrier and AMCs not started yet

(IPMI) Hardware Issues - DHH Shelf (2Slot)



(IPMI) Hardware Issues - DHH Shelf (2Slot)

Sensor Information

Sensor Data Information

Type: Discrete (0x6f), "Hot Swap" (0xf0) Belongs to entity (0x15, 0x61): FRU # 1

All event messages enabled from this sensor

All event messages enabled from this sensor

All event messages enabled from this sensor

66: LUN: 0, Sensor # 0 ("PEMA Hot Swap")

Sensor scanning enabled

Initial update completed

66: LUN: 0, Sensor # 1 ("PEMB Hot Swap")

Sensor scanning enabled

Initial update completed

66: LUN: 0, Sensor # 2 ("PEM IPMB LINK")

Sensor scanning enabled Initial update completed

Type: Discrete (0x6f), "Hot Swap" (0xf0)

Belongs to entity (0x15, 0x62): FRU # 2

Type: Discrete (0x6f), "IPMB Link" (0xf1) Belongs to entity (0x15, 0x60): FRU # 0

Verbose mode turned on

Verbose mode turned on

Sensor reading: 0x00

Sensor reading: 0x00

Sensor reading: 0x88 Current State Mask 0x0008

Current State Mask 0x0004

Current State Mask 0x0004

Status: 0xc0

Status: 0xc0

Status: 0xc0

- 66: LUN: 0, Sensor # 0 ("PEMA Hot Swap")
 Type: Discrete (0x6f), "Hot Swap" (0xf0)
 Belongs to entity (0x15, 97): [FRU # 1]
 Assertion Mask: 0x00ff
 Deassertion Mask: 0x0000
 Settable / Readable Mask: 0x00ff
- 66: LUN: 0, Sensor # 1 ("PEMB Hot Swap")
 Type: Discrete (0x6f), "Hot Swap" (0xf0)
 Belongs to entity (0x15, 98): [FRU # 2]
 Assertion Mask: 0x00ff
 Deassertion Mask: 0x0000
 Settable / Readable Mask: 0x00ff
- 66: LUN: 0, Sensor # 2 ("PEM IPMB LINK")
 Type: Discrete (0x6f), "IPMB Link" (0xf1)
 Belongs to entity (0x15, 96): [FRU # 0]
 Assertion Mask: 0x000f
 Deassertion Mask: 0x0000
 Settable / Readable Mask: 0x000f

FRU Information

66: FRU # 0

Entity: (0x15, 0x60)

Hot Swap State: M4 (Active), Previous: M7 (Communication Lost), Last State Change Cause: Communication Lost (0x4) Device ID String: "PEM IPMC"

Entity: (0x15, 0x61) Hot Swap State: M4 (Active), Previous: M7 (Communication Lost), Last State Change Cause: Communication Lost (0x4) Device ID String: "PEMA"

66: FRU # 2

Entity: (0x15, 0x62) Hot Swap State: M4 (Active), Previous: M7 (Communication Lost), Last State Change Cause: Communication Lost (0x4) Device ID String: "PEMB"

B. Spruck, Uni Mainz, 9.4.2018, p. 9

Sensor reading ("Mask") tells M2, but Shelf Manager reports M4 state. (ShM keeps Track of Messages; but IPMI ioc uses sensor reading)


Clearly a firmware problem (or a questionable implementation) on the FRU ...

But on several at the same time???

^{66:} FRU # 1

(IPMI) Hardware Issues - ONSEN Shelf

JOHANNES GUTENBERG UNIVERSITÄT MAINZ



No Power Supply, that is strange.

(IPMI) Hardware Issues – ONSEN Shelf

JOHANNES GUTENBERG UNIVERSITÄT MAINZ


JGU

🏢 Message History (ES) 🛛	
--------------------------	--

Start:	-1 hour			End: no	w		Times	ilter 🔗
CREA	TETIME	DELTA	SEVER	TEXT	APPLICATION-I	NAME	USE	HOS.
2017-	12-20 22:55:53.665	00:00:00	INFO	sensor 0x5a/Fan Tach 6: Read valid again.	ipmi-sensor-IOA	static void IPMIIOC::Device::aiCallback(CALLBACK	*) epics	s pxdioc
2017-	12-20 22:55:53.653	00:00:00	INFO	sensor 0x5a/Fan Tach 5: Read valid again.	ipmi-sensor-IOA	static void IPMIIOC::Device::aiCallback(CALLBACK	*) epics	s p×dioc
2017-	12-20 22:55:53.641	00:00:00	INFO	sensor 0x5a/Fan Tach 4: Read valid again.	ipmi-sensor-IOA	static void IPMIIOC::Device::aiCallback(CALLBACK	*) epics	s pxdioc
2017-	12-20 22:55:53.628	00:00:00	INFO	sensor 0x5a/Fan Tach 3: Read valid again.	ipmi-sensor-IOA	static void IPMIIOC::Device::aiCallback(CALLBACK	*) epics	s p×dioc
2017-	12-20 22:55:53.616	00:00:00	INFO	sensor 0x5a/Fan Tach 2: Read valid again.	ipmi-sensor-IOA	static void IPMIIOC::Device::aiCallback(CALLBACK	*) epics	s p×dioc
2017-	12-20 22:55:53.606	00:00:2!	INFO	sensor 0x5a/Fan Tach 1: Read valid again.	ipmi-sensor-IOA	static void IPMIIOC::Device::aiCallback(CALLBACK	*) epics	s pxdioc
2017-	12-20 22:55:23.690	00:00:00	WARNIN	sensor 0x5a/Fan Tach 8: Read invalid.	ipmi-sensor-IOA	static void IPMIIOC::Device::aiCallback(CALLBACK	*) epics	s pxdioc
2017-	12-20 22:55:23.678	00:00:00	WARNIN	sensor 0x5a/Fan Tach 7: Read invalid.	ipmi-sensor-IOA	static void IPMIIOC::Device::aiCallback(CALLBACK	*) epics	s pxdioc
2017-	12-20 22:55:23.666	00:00:00	WARNIN	sensor 0x5a/Fan Tach 6: Read invalid.	ipmi-sensor-IOA	static void IPMIIOC::Device::aiCallback(CALLBACK	*) epics	s p×dioc
2017-	12-20 22:55:23.656	00:00:00	WARNIN	sensor 0x5a/Fan Tach 5: Read invalid.	ipmi-sensor-IOA	static void IPMIIOC::Device::aiCallback(CALLBACK	*) epics	s pxdioc
2017-	12-20 22:55:23.644	00:00:00	WARNIN	sensor 0x5a/Fan Tach 4: Read invalid.	ipmi-sensor-IOA	static void IPMIIOC::Device::aiCallback(CALLBACK	*) epics	s p×dioc
2017-	12-20 22:55:23.632	00:00:00	WARNIN	sensor 0x5a/Fan Tach 3: Read invalid.	ipmi-sensor-IOA	static void IPMIIOC::Device::aiCallback(CALLBACK	*) epics	s p×dioc
2017-	12-20 22:55:23.620	00:00:00	WARNIN	sensor 0x5a/Fan Tach 2: Read invalid.	ipmi-sensor-IOA	static void IPMIIOC::Device::aiCallback(CALLBACK	*) epics	s pxdioc
2017-	12-20 22:55:23.608	00:00:4	WARNIN	sensor 0x5a/Fan Tach 1: Read invalid.	ipmi-sensor-IOA	static void IPMIIOC::Device::aiCallback(CALLBACK	*) epics	s p×dioc

Every O(10) minutes read problems on fan sensors... recovering on the SCAN / next readout cycle. Reason unclear, no indication of problems in the ShM SEL log.

We did not observe this with the "Lab" or "Final" Shelf in GI or DESY.



JOHANNES GUTENBERG

UNIVERSITÄT MAINZ

JGU

Old picture, but "problem" can be reproduced in current setup. Remark: Its only a (cosmetic) GUI issue.

- Old: ONSEN Firmware required "abort → not ready → loading" sequence before each run.
 - This has been fixed. Cycle "ready→ start → running → stop → ready" is now working as expected by run control.

JOHANNES GUTENBERG

- $EB/HLT \rightarrow ONSEN$ race conditions:
 - Old: EB/HLT could connect before the TCP was initialized.
 - Rework activation + deactivation of links (TCP/IP and Aurora) to prevent race conditions between sub-systems and disconnected TCP/IP connections (timeouts).