

# RunControl @ EPICS 3.16.1

- Changes in EPICS observed in Oct. 2017
  - States are not propagated to subsystems correctly, seem stuck
- RC uses “dfanout” record to push requested state to multiple sub systems
- “OUT” field is not allowed to be CPP (channel access, post-processing)
- Changing this to correct values solve the problem
  - “CA” for other IOCs (post-processing is done automatically)
  - “PP” in the same IOC
- State machine on PowerPC (used in ONSSEN) does not work correctly
  - outsourcing possible and already tested in Giessen lab